

MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY BREATH ALCOHOL PROGRAM CMI INTOXILYZER 5000 MAINTENANCE REPORT

RECEIVED By Carol Day at 1:20 pm, Apr 07, 2014

		and the second company of the second company		
Complete this report at the time of the regular monthly preventive maintenance check (not to exceed 35 days). Complete this report whenever the instrument is serviced or repaired and whenever it is placed into service. Retain the original and send a copy within 15 days to the Breath Alcohol Program, DHSS.				
INTOXILYZEH SEED SN HAME OF AGENCY 507/4 SKCC	vity Forces		DATE OF INSPECTION	014
1031 VOADEN LISTAGET MID CITY,	, 1/	4/13	LIME OF INSPECTION / S / S	
CHECKLIST: Place a markuby each item if for where determined.) Unmarked items must be	ound to be satisfactory o		established limits. (Writ	e in observed values
DVM TEST: (.350 ± .150)		msturrent,	emeller mere angele engly vicer wire dig version and all characteristics.	
DIAGNOSTIC CHECK (PRINTOUT ATT	ACHED) HASSEU	DATE AND TIME (FROM PRINTOUT) 🖔	14/14
CHARACTER DISPLAY TEST	Posseo			
PRINT TEST (PRINTOUT ATTACHED)	Passed	10.47 (1100./100./100.001.0		
\square SIMULATOR SOLUTION SUPPLIER $\mathcal G$	whilabs Inc	LOT # /	4030 EXP.	DATE 1/20/16
SIMULATOR TEMPERATURE (34°C ± 0	2°C) 34/6 C	SIMULATOR SN	<i>SOI/S'</i> 7 EXP.	DATE <u>09/10/14</u>
CALIBRATION CHECK - (ONLY ONE S'	TANDARD IS TO BE US	SED PER MAINTEN	ANCE REPORT)	
Run three tests using a standard solution, All three tests must be within ± 5% of the standard value and must have a spread of .005 or less. Mark the box corresponding to the standard solution being used. (PRINTOUT ATTACHED) 0.100% STANDARD • MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE 0.080% STANDARD • MUST READ BETWEEN 0.076% AND 0.084% INCLUSIVE				
☐ 0.040% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE				
TEST 1	TEST 2 •	75	TEST 3 ♥ , O	97
M PERFORM RELIEST (PRINTOUT ATTACHED) REI Defected				
INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT: (DO NOT INCLUDE SELF-ADMINISTERED TESTS)				
REFUSALS Ø 004	.0509	.1014	.1519	Over .19
LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION OR M (USE OTHER SIDE IF NECESSARY).	ODIFICATION THAT WAS MADE TO	D RESTORE THE INSTRUMEN	IT TO OPERATE SATISFACTORI	LY AND WITHIN ESTABLISHED LIMITS
INSPECTING OFFICER		PRINT FUEL NAV	JE V W/ U/	
TOUR DESCRIPTION OF THE SOUTH STATE OF THE SOUTH ST	WY 5	131/14 181804938 711 (000	<u>K Marnet</u> 687 587	14 V
RETURN COMPLETED REPORT TO THE:	Breath Alcohol Progra Southeast District Off 2875 James Blvd.		nent of Health and Sen	nior Services

Poplar Bluff, MO 63901

Sometimes of the second second



CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 14030 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography on January 22, 2014, using a Perkin Elmer Gas Chromatograph Autosystem XL S/N: 610N9030209, and found to contain 0.1215% (w/vol) ethyl alcohol. The expiration date for this lot number is January 20, 2016 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol analysis instrument reading of 0.100 g/210L +/- 3%.

The alcohol and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

NIST Traceability:

Testing was conducted using Cerilliant Reference Standard lot number FN122211-02 whose values are traceable to NIST.

All balances are calibrated annually by an outside agency using NIST traceable weights. Calibration verification is done prior to each use utilizing NIST traceable weights.

THIS SIDE UP, THIS EDGE IN. FORM NUMBER 015010

WHITEMAN AFB INTOXILYZER - ALCOHOL ANALYZER MO MODEL 5000 SN 66-005259 04/04/2014

DIAGNOSTIC TEST

15:53

PROM CHECK E735.23	PASSED
RAM CHECK	PASSED
TEMP CHECK	PASSED
PROCESSOR CHECK	
SYNC PULSE	PASSED
SYNC SPEED	PASSED
NEG STABILITY	PASSED
NEG STABILITY POS STABILITY	PASSED
REF RANGE	PASSED

DIAGNOSTIC

PASSED

PRINTER CHECK ABCDEFGHIJKLMNOPORSTUVWXYZ 0123456789

SUBJECTS NAME

1 11 1.

7

OPERATORI

RO/GIVA MOITAMROTALI JAHORIDO

INTOXILYZER! INSTRUMENT PRINTER CARD

TAME FORST OBSERVED

© 1988 by CMIINC.

THIS SIDE UP. THIS EDGE IN. FORM NUMBER 015010

SN 66-005259 E735.23

04/04/2014 15:54

ABCDEFGHIJKLMNOPGRSTUUWXYZ0123
ABCDEFGHIJKLMNOPGRSTUUWXYZ0123456789
ABCDEFGHIJKLMNOPGRSTUWXYZ01234567891384abcde
ABCDEFGHIJKLMNOPGRSTUU
ABCDEFGHIJKLMNOPGRSTUU
ABCDEFGHIJKLMNOPGRSTUU
ABCDEFGHIJKLMNOPGRSTUU
ABCDEFGHIJKLMNOPGRSTUU

SUBJECTS HAME	
BULL WALL OFF PATOR RATION AND/OR R	PASTRUMENT LOCATION LA EMAPOS
TOXILYZER ^{3,} INSTRUMENT PRINTER CARD	emi.

© 1986 by CMUINC.

THIS SIDE UP, THIS EDGE IN, FORM NUMBER O 180 TO
State of the state
SN 66-005259 04/04/2014 E735.23 15:58 INVALID TEST INHIBITED - RFI
E735, 23
INVALID TEST
INHIBITED - KLT
•
•
41
· ·
•
•
· ·
•
•
SUBJECT'S NAME
PASTAULARN LUCCATION
TUXE FIRST CRISERYED
15/11/11/9/11
OPENATOR
A FOOT CHALL THE OFFINATION AND/OR REMARKS
INTOXILYZER ¹ INSTRUMENT PRINTER CARD
######################################

@ 1986 by CMI INC.

THIS SIDE UP. THIS EDGE IN. FORM NUMBER 0 150 10

WHITEMAN AFB
INTOXILYZER - ALCOHOL ANALYZER
MO MODEL 5000 SN 66-005259
04/04/2014

TEST	%BAC	TIME
AIR BLANK	.000	16:05
CAL. CHECK	.097	16:06
AIR BLANK	.000	16:06
CAL. CHECK	. 095	16:06
AIR BLANK	. 000	16:07
CAL. CHECK	. 097	16:07
AIR BLANK	. 000	16:07

NO RFI PRESENT

SUBJECTS NAME

ILLE FIRST OSSERYTO OSSERVE LOCATION

OPERATOR

ADDITIONAL INFORMATION AND/OR REMARKS

INTOXILYZER® INSTRUMENT PRINTER CARD

© 1986 by CMI INC.

State of Missouri DEPARTMENT OF HEALTH



PERMIT TYPE II



BILLY R MATHENY

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

INTOXILYZER 5000

for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986.

Date 04/24/2012	Was hotel
Number 220098	Director of State Public Health Laboratory Mangart 1. Drunckly
Expires <u>04/24/2014</u>	Director, Department of Health
MO 580-0771 (7-88)	Lab. 4 (A7-88)